



Hayle Harbour

Environmental Statement

Volume 3 Technical Annexes 13



November 2007

ING RED UK (Hayle Harbour) Limited

Contents

Volume 3

Technical Annexes 13 Water Resources

Technical Annex 13A	Harbour Wall Condition Survey Draft Report
Technical Annex 13A	(Part A) Harbour Wall Condition Survey Plan
Technical Annex 13B	Sediment Exchange Monitoring Report
Technical Annex 13C	Harbour Wall Schedule of Works Report
Technical Annex 13D	Report on the Mechanical Survey of the Copperhouse Sluice Vertical Lift Gate
Technical Annex 13E	Pool Level Factual Information
Technical Annex 13F	Hydraulic Studies Phase 2
Technical Annex 13G	Harbour Works Description
Technical Annex 13H	Flood Risk Assessment